

Figure E.41 Time Step of Surface Corrosion for 0.0% Chloride Post-Cracked Specimens




Figure E.42 Time Step of Rib Loss for 0.0% Chloride Post-Cracked Specimens